

HAER
CAL
40-SANMAR.V,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Salinas Dam
Salinas River, 1½ miles northeast of Pozo Road,
3½ miles east of the intersection with State Route 58
Santa Margarita Vicinity
San Luis Obispo County
California

HAER No. CA- 183

Bill Dewey, Photographer

December 1996

- CA-183-1 CONTEXTUAL VIEW. CAMERA FACING SOUTHEAST.
- CA-183-2 CONTEXTUAL VIEW. CAMERA FACING NORTHEAST.
- CA-183-3 TOP OF THE SPILLWAY AND CONCRETE FILL. CAMERA FACING SOUTH.
- CA-183-4 LEFT (EAST) BUTTRESS. CAMERA FACING SOUTH.
- CA-183-5 RIGHT (WEST) BUTTRESS. CAMERA FACING EAST.
- CA-183-6 SPILLWAY AT THE RIGHT OF THE DAM, TIED STRUCTURALLY TO THE
RIGHT (WEST) BUTTRESS. CAMERA FACING SOUTH.
- CA-183-7 SPILLWAY CHUTE. CAMERA FACING NORTH.
- CA-183-8 ROCK FACE TREATED WITH GUNITE TO PREVENT EROSION. CAMERA
FACING SOUTHEAST.
- CA-183-9 CATWALK. CAMERA FACING NORTHEAST.
- CA-183-10 DIAGONAL STAIRWAY AND DOORWAY. CAMERA FACING NORTH.
- CA-183-11 DIAGONAL STAIRWAY. CAMERA FACING SOUTH.
- CA-183-12 CONCRETE STAIRWAY LEADING TO A LANDING BUILT TO HOUSE THE
MACHINERY AND COUNTERWEIGHT FOR THE DRUM GATE WHICH WAS
NEVER INSTALLED, INSIDE THE RIGHT (WEST) BUTTRESS. CAMERA FACING
NORTH.
- CA-183-13 MASS OF POURED CONCRETE IN IRREGULAR STEPPED LAYERS AT THE BASE
OF THE LEFT (EAST) BUTTRESS. CAMERA FACING SOUTHWEST.
- CA-183-14 LONG LADDER EMBEDDED IN THE DAM FACE ON THE LEFT (EAST) SIDE OF
THE DAM. CAMERA FACING SOUTH.

SALINAS DAM
HAER No. CA-183
INDEX TO PHOTOGRAPHS (page 2)

- CA-183-15 LARGE CONCRETE STRUTS LOCATED IN THE RIVER BED BELOW THE RIGHT BUTTRESS AND SLIGHTLY UPSTREAM FROM THE SPILLWAY. CAMERA FACING EAST.
- CA-183-16 LOWER LEVEL EMERGENCY SPILLWAY. CAMERA FACING SOUTH.
- CA-183-17 INTAKE PIPES ON THE RIGHT BUTTRESS USED TO SPILL WATER INTO THE SALINAS RIVER. CAMERA FACING NORTH.
- CA-183-18 INTAKE PIPES ON THE RIGHT BUTTRESS USED TO SPILL WATER INTO THE SALINAS RIVER. CAMERA FACING NORTHEAST.
- CA-183-19 BOOMS AND WINCHES TO CONTROL FLEXIBLE TUBES. CAMERA FACING NORTH.
- CA-183-20 STILING WELL. CAMERA FACING NORTH.
- CA-183-21 Photocopy of original photo from Corps of Engineers, Los Angeles District, "Report on Salinas Dam, Salinas River, California," June 15, 1943. (Photographer unknown; report located at City of San Luis Obispo.) SALINAS DAM UNDER CONSTRUCTION IN 1941.
- CA-183-22 Photocopy of original photo from Corps of Engineers, Los Angeles District, "Report on Salinas Dam, Salinas River, California," June 15, 1943. (Photographer unknown; report located at City of San Luis Obispo.) CONSTRUCTION PHOTO SHOWING THE STRUTS, POURED TO ALIGN WITH THE RIGHT (WEST) BUTTRESS.
- CA-183-23 Photocopy of original photo from Corps of Engineers, Los Angeles District, "Report on Salinas Dam, Salinas River, California," June 15, 1943. (Photographer unknown; report located at City of San Luis Obispo.) CONSTRUCTION PHOTO SHOWING CURVED CONCRETE CHUTE SPILLWAY.
- CA-183-24 Photocopy of original photo from Corps of Engineers, Los Angeles District, "Report on Salinas Dam, Salinas River, California," June 15, 1943. (Photographer unknown; report located at City of San Luis Obispo.) SALINAS DAM COMPLETION PHOTO.
- CA-183-25 Photocopy of engineering drawing by Leeds, Hill, Barnard, and Jewitt, Architect-Engineer (original drawing located at County of San Luis Obispo). SALINAS DAM PLAN AND SECTIONS.
- CA-183-26 Photocopy of engineering drawing by Leeds, Hill, Barnard, and Jewitt, Architect-Engineer (original drawing located at County of San Luis Obispo) SALINAS DAM ROOFING PLAN.

SALINAS DAM
HAER No. CA-183
INDEX TO PHOTOGRAPHS (page 3)

CA-183-27 Photocopy of engineering drawing by Leeds, Hill, Barnard, and Jewitt, Architect-Engineer(original drawing located at County of San Luis Obispo). STRUT LAYOUT -- RIGHT ABUTMENT.